GOVERNMENT OF ANDHRA PRADESH ABSTRACT

Panchayat Raj Department – West Godavari District – Minor Repairs of 48 Cyclone Shelters in Bhimadol Mandal, West Godavari District – Administrative Sanction accorded – Orders – Issued.

PANCHAYAT RAJ & RURAL DEVELOPMENT (PROGS.III) DEPARTMENT

G.O.Rt.No. 1322 <u>Dated:-17.07.2012</u> Read the following:

1. From the Chief Engineer(PR), Hyderabad Lr No.AEE7/DEE2/C.M.assurance/2011 dated 28.3.20112 &&&

ORDER:

In the reference 1^{st} read above, the Chief Engineer (PR) submitted proposal for Minor Repairs of 48 Cyclone Shelters in Bhimadol Mandal, West Godavari District with an estimated cost of Rs.115.30 lakh as additional funds under Assistance to PRI for Maintenance of Cyclone shelters.

2. Government after careful examination of the proposal hereby accord administrative sanction for Minor Repairs of 48 Cyclone Shelters in Bhimadol Mandal, West Godavari District with an estimated cost of Rs.115.30 lakh (Rupees One crore Fifteen lakh and Thirty Thousand only) under Assistance to PRIs for Maintenance of Cyclone shelters as per the details of works shown in Annexure Appended to this GO and debited to the following Head of Account;

МЛЦ	2515		Other Rural Development
ו וכויו	2313	=	Other Rural Development
			Programmes
MH	196	-	Assistance to Zilla Parishads
SH	(14)	-	Assistance to Panchayat Raj
			Institutions for Maintenance of
			Cyclone Shelters
	270	-	Minor works
	272	-	Maintenance

- 3. The Chief Engineer, Panchayat Raj, Hyderabad shall take necessary action accordingly.
- 4. This order issues with the concurrence of Finance (Expr.PR&RD) Dept. vide their U.O.No.17217/370/12 Expr.PR&RD dated.7.7.2012.
- 5. A copy of this order is available on the internet and can be accessed at the address: www.ap.gov.in/goir.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

C.R.BISWAL PRINCIPAL SECRETARY TO GOVERNMENT

Tο

The Chief Engineer, Panchayat Raj, Hyderabad.

The Superintending Engineer (PR), Eluru, West Godavari District

The Accountant General, A.P., Hyderabad.

The Director of Treasuries & Accounts, A.P. Hyderabad.

The Director of works and Accounts, Hyderabad.

Copy to:

The P.S to Minister (P.R.).

P.S to Principal Secretary (PR)

The Finance (Expr.PR&RD) Dept. SF/SC.

//FORWARDED::BY ORDER//

SECTION OFFICER

(TO THE G.O.RT.NO. 1322 PR&RD (PROGS.III) DEPT. DATED:17.07.2012)

S.No.	Name of the	Name of the work	Est. Cost Rs.in
S.INO.	Mandal	Name of the work	lakh
1	Narsapur	Repairs to Cyclone Shelter at Ramanjaneyapuram of Vamuladeevi	1.00
2	Narsapur	Repairs to Cyclone Shelter at Sarva	1.00
3	Narsapur	Repairs to Cyclone Shelter at Vaddivarimeraka of Vemuladeevi West	2.00
4	Narsapur	Repairs to Cyclone Shelter at sub Collector Office Compound in Narsapuram	2.00
5	Narsapur	Repairs to Cyclone Shelter at Vegiwarimalapalli of Vemuladeevi West	2.00
6	Narsapur	Repairs to Cyclone Shelter at Sriramnagar of Biyyaputippa	2.00
7	Narsapur	Repairs to Cyclone Shelter at Chamakurupalem	2.00
8	Narsapur	Repairs to Cyclone Shelter atBynapalem of L.B.cherla	3.00
9	Narsapur	Repairs to Cyclone Shelter at Biyyaputippa-II	1.00
10	Narsapur	Repairs to Cyclone Shelter at Bandarivari harijanapeta (Pedathota) of Turputallu	200
11	Narsapur	Repairs to Cyclone Shelter at Chinamynavanilanka of Vemuladeevi West	2.00
12	Narsapur	Repairs to Cyclone Shelter at Dharbharevu	2.50
13	Narsapur	Repairs to Cyclone Shelter at Gondimula of Vemuladeevi West	2.00
14	Narsapur	Repairs to Cyclone Shelter at Rajula Lanka	1.00
15	Narsapur	Repairs to Cyclone Shelter at Pallipalem of Vemuladeevi	2.00
16	Narsapur	Repairs to Cyclone Shelter at Pedamynavanilaknka-I	2.00
17	Narsapur	Repairs to Cyclone Shelter at Prdkashpuram of Vemuladeevi	4.00
18	Narsapur	Repairs to Cyclone Shelter at Karimsettivaripalem of Turputallu	3.00
19	Narsapur	Repairs to Cyclone Shelter at Madhvaipalem of Narsapur	2.00
20	Narsapur	Repairs to Cyclone Shelter at Marritippa	2.00
21	Narsapur	Repairs to Cyclone Shelter at Modi of Chamakuripaelm	2.00
22	Mogaltur	Repairs to Cyclone Shelter at Gedallavampu of Mutylapalli	1.50
23	Mogaltur	Repairs to Cyclone Shelter at Dibbalapallipalem of Perupalem (South)	7.00
24	Mogaltur	Repairs to Cyclone Shelter at Allamvbrimeraka of K.P.Palem North	2.00
25	Mogaltur	Repairs to Cyclone Shelter at Chintarevu 1 of Mutylapalli	1.50
26	Mogaltur	Repairs to Cyclone Shelter atGuntapallavapaelm of Mogaltur	2.00
27	Mogaltur	Repairs to Cyclone Shelter at Harijanawada of Kalipatnam east	2.00
28	Mogaltur	Repairs to Cyclone Shelter at Harijanawada of Kothota	1.00
29	Mogaltur	Repairs to Cyclone Shelter at Jilleduthippa of Kothota	5.00
30	Mogaltur	Repairs to Cyclone Shelter at kothakayalathippa of Mogaltur	1.80

31	Mogaltur	Repairs to Cyclone Shelter at Marrithippa of 3.00 Jaggnadhapuram			
32	Mogaltur	Repairs to Cyclone Shelter at Mandavari thota of Ramannapalem	3.00		
33	Mogaltur	Repairs to Cyclone Shelter at Metturevu of K.P. Palem North	1.00		
34	Mogaltur	Repairs to Cyclone Shelter at Neethitippa of Komatithippa	2.50		
35	Mogaltur	Repairs to Cyclone Shelter at Palakamma Cheruvu of Mogaltur	3.00		
36	Mogaltur	Repairs to Cyclone Shelter at Warathippa of Mogaltur	2.00		
37	Mogaltur	Repairs to Cyclone Shelter at Pathapadu	2.00		
38	Mogaltur	Repairs to Cyclone Shelter at Mutylapalli	2.00		
39	Mogaltur	Repairs to Cyclone Shelter at Mollaparru of Perupaelm (S)	12.00		
40	Bhimavaram	Repairs to Cyclone Shelter Building at Kothapusalamarru (V)	2.00		
41	Akividu	Repairs to Cyclone Shelter Building at Siddapuram (V)	5.00		
42	Elamanchili	Repairs to Cyclone Shelter Building at Kanakayalanka	4.00		
43	Achanta	Repairs to Cyclone Shelter Building at Gudivakalanka	0.50		
44	Eluru	Repairs to Cyclone Shelter Building at Marrimula of Ayodhya Lanka.	1.00		
45	Eluru	Repairs to Cyclone Shelter Building at Prathikollanka	1.00		
46	Eluru	Repairs to Cyclone Shelter Building at Pydichintapadu	1.00		
47	Eluru	Repairs to Cyclone Shelter Building at Yaganamalli	1.00		
48	Bhimadole	Repairs to Cyclone Shelter Building at Mallavaram H/o Chettunnapadu	3.00		
		Total	115.30		

C.R.BISWAL PRINCIPAL SECRETARY TO GOVERNMENT

SECTION OFFICER